



Predmet:
080824-5760

Klasifikacija:
Prometni znakovi i signalizacija

Datum predmeta:
08.August.2024 u 10:44

Izvor predmeta:




Pavković Renato (Građanin)

Opis:

na priloženoj slici vidljivo zamučeno prometno ogledalo, nije moguće vidjeti nadolazeće vozilo.

Adresa:
Rimski put 43a
Trogir 21220

Geokoordinate:
43°31'29"N
16°15'03"E



Slike:

