



Predmet:

090924-34369

Klasifikacija:

Oštećenje urbane opreme (košarice za otpad, klupice, autobusne čekaonice, javni satovi, fontane)

Datum predmeta:

09.September.2024 u 12:58

Izvor predmeta:



Marčelja Sanja (Građanin)

Opis:


na klupi za sjedenje su razbijene dvije daske

Adresa:

Medovićeva ulica 19
Rijeka 51000

Geokoordinate:

45°20'40"N
14°23'48"E



Slike:

