




Predmet:
171024-5812

Klasifikacija:
Oštećenje javnih površina


Datum predmeta:
17.October.2024 u 11:53

Izvor predmeta:
 Vidovic Maja (Građanin)

Opis:
Razbijeno staklo na autobusnoj stanici

Adresa:
Trg Brce 1
Žedno 21220

Geokoordinate:
43°30'17"N
16°17'24"E



Slike:

