




Predmet:
180624-33527

Klasifikacija:
Oštećenja/rubnjaci, prometna
signalizacija,


Datum predmeta:
18.June.2024 u 15:41

Izvor predmeta:
 Slanina Lukić Martina
(Građanin)

Opis:
Pored šahte je kolnik oštećen do te mjere da iz rupe viri oštra armatura koja može oštetiti automobilsku gumu.

Adresa:
Baštijanova ulica 66
Rijeka 51000

Geokoordinate:
45°19'57"N
14°26'46"E



Slike:

