



Predmet:
190425-38557

Klasifikacija:
Prometni znak, stupići, betonske gljive


Datum predmeta:
19.April.2025 u 11:28

Izvor predmeta:
 111 Marko (Gračanin)

Opis:
Oštećenje plastičnih stupića (čupanje, savijanje, trganje) uslijed prolaska vozila. Mogućnost udaranja vozila u stupiće. Narušena estetska vizura.

Adresa:
Trg Riječke Rezolucije 3
Rijeka 51000

Geokoordinate:
45°19'39"N
14°26'31"E



Slike:

