



Predmet:

200425-38566

Klasifikacija:

Oštećenje urbane opreme (košarice za otpad, klupice, autobusne čekaonice, javni satovi, fontane)

Datum predmeta:

20.April.2025 u 19:36

Izvor predmeta:



Kusic Doris (Građanin)

Opis:


razbijena klupa,

Adresa:

Ulica Drage Šćitara 2  
Rijeka 51000

Geokoordinate:

45°19'28"N  
14°27'55"E



Slike:

