



Predmet:  
210125-5878

Klasifikacija:  
Prometni znakovi i signalizacija

Datum predmeta:  
21.January.2025 u 19:45

Izvor predmeta:




Kuzmanić Lidija (Građanin)

Opis:

opasna rupa u kojoj upada kolo od aute. ljudi pokušavaju izbjeći rupu i ulaze u drugu traku, dogodit ce se sudar, potrebno je rupu prekriti asfaltom.

Adresa:  
Put Gradine 6  
Trogir 21220

Geokoordinate:  
43°30'57"N  
16°15'23"E



Slike:

