



Predmet:
210425-38572

Klasifikacija:
Uklanjanje nepoželjne vegetacije i
orezivanje zelenila

Datum predmeta:
21.April.2025 u 09:23

Izvor predmeta:




Šajn Doris (Građanin)

Opis:

Stepenice su jako ostećene i napukle. Korov i trava su se prosirili po stepenicama iz zelenila po rubu stepenica. Dosta otpada po stepenicama i okolišu.

Adresa:
Save Vukelića 31
Rijeka 51000

Geokoordinate:
45°20'59"N
14°25'16"E



Slike:

