




Predmet:
211122-4099

Klasifikacija:
Građevinska inspekcija

Datum predmeta:
21.November.2022 u 21:22


Izvor predmeta:
 Škrlj Karmen (Građanin)

Opis:

Poštovani, u malom parku, neposredno iza zgrade predviđene za rušenje i ispred koje se nalaze kante za otpad uočena je velika količina drvenog materijala, salonitnih ploča i ostalog otpadnog materijala.

Adresa:
Dr. Ante Starčevića 80
Trogir 21220

Geokoordinate:
43°31'22"N
16°15'33"E



Slike:

