



Predmet:
211124-8955

Klasifikacija:
Nije klasificiran!

Datum predmeta:
21.November.2024 u 15:37

Izvor predmeta:



Željko Fajdetić

Opis:


U ulici glagoljaša 23 na kolniku je udarna rupa, prekopan kolnik i to treba sanirati

Adresa:

Glagoljaša ulica 31
Crikvenica 51260

Geokoordinate:

45°10'25"N
14°41'47"E



Slike:

