



Predmet:

221024-35062

Klasifikacija:

Oštećenje urbane opreme (košarice za otpad, klupice, autobusne čekaonice, javni satovi, fontane)

Datum predmeta:

22.October.2024 u 08:43

Izvor predmeta:



Andric Marko (Građanin)

Opis:


Sve tri klupe posarane sa sprejem.

Adresa:

Ulica Slavka Krautzeka 84  
Rijeka 51000

Geokoordinate:

45°19'29"N  
14°27'58"E



Slike:

