



Predmet:  
230424-32703

Klasifikacija:  
Prekopi/prometnice, nogostupi

Datum predmeta:  
23.April.2024 u 19:06

Izvor predmeta:




Perinić Ivica (Građanin)

Opis:

Na putu koji spaja Kvaternikovu (bro zgrade 46, s zadnje strane), i Radničku ulicu, na Podvežici, nastala je rupa promjera, cca 50 cm i dubine do 15 cm. Opasna je za pješake kao i za vozila koja ovdje prolaze. To treba žurno sanirati.

Adresa:  
Kvaternikova 71  
Rijeka 51000

Geokoordinate:  
45°19'16"N  
14°28'34"E



Slike:

