




Predmet:
240524-5673

Klasifikacija:
Građevinska inspekcija


Datum predmeta:
24.May.2024 u 08:54

Izvor predmeta:
 Rogulj Anita (Građanin)

Opis:
nakon popravka nogostupa nije moguće otvoriti sahtu od vode

Adresa:
Obala kralja Zvonimira 5
Trogir 21220

Geokoordinate:
43°30'54"N
16°15'09"E



Slike:

