



Predmet:
250224-21837

Klasifikacija:
Nije klasificiran!

Datum predmeta:
25. February.2024 u 19:44

Izvor predmeta:




Martina Augustinović

Opis:

Kombinacija betona i asfalta oko kanalizacijskoga šahta se urušava te se dvije rupe neprestano povećavaju stvarajući opasnost za pješake.

Adresa:
Zelenice ulica 25
Labin 52220

Geokoordinate:
45°05'33"N
14°07'22"E



Slike:

