



Predmet:
260224-21845

Klasifikacija:
Nije klasificiran!

Datum predmeta:
26. February.2024 u 22:53

Izvor predmeta:




Martina Augustinović

Opis:

Oko kanalizacijskog šahta na pločniku se urušava beton i asfalt te se rupe neprestano povećavaju stvarajući opasnost za veliki broj pješaka koji tuda svakodnevno prolazi.

Adresa:
Zelenice ulica 25
Labin 52220

Geokoordinate:
45°05'33"N
14°07'22"E



Slike:

