




Predmet:  
270624-33578

Klasifikacija:  
Oštećenja/rubnjaci, prometna  
signalizacija,

Datum predmeta:  
27.June.2024 u 10:05


Izvor predmeta:  
 Milovanović Daniela  
(Građanin)

Opis:

Velika rupa na kolniku i par manjih rupa na istom kolniku, što otežava kretanje vozila i pri parkiranju te postoji velika mogućnost oštećenja vozila i okolnih vozila i prolaznika radi kamenja koja frcaju na sve strane kad se upadne u rupu i zašljafa guma. Kako se rupa nalazi više na lijevoj strani teško ju je za izbijeći. Pošto je kraj nas vrtić stalno dolaze vozila i dostavna vozila pa se rupa stalno širi.

Adresa:  
Ulica Franje Čandeka 24  
Rijeka 51000

Geokoordinate:  
45°20'25"N  
14°24'41"E



Slike:

